delta Q

delta I

Start: state at 0

Step: measure feedthrough for each possible next state and
                transition to the one with lowest feedthrough

Termination: no lower feedthrough can be reached or 24 transitions have been done